

X represents pseudo range measurements

Fig. 3






FIG. 4




Single point measurement results

FIG. 5




Five point position averaging

FIG. 6




Ten point position averaging

FIG. 7



Five point pseudo range averaging

FIG. 8



Ten point pseudo range averaging

FIG. 9